



**REPORT ON THE AWARD OF CONSTRUCTION CONTRACTS AND CHANGES TO CONSTRUCTION
CONTRACTS FOR THE BOARD OF EDUCATION'S CAPITAL IMPROVEMENT PROGRAM**

THE CHIEF EXECUTIVE OFFICER REPORTS THE FOLLOWING DECISION:

This report details the award of Capital Improvement Program construction contracts in the total amount



~~\$610,201,200.50 to the respective lowest responsible bidders for various capital improvement projects.~~



GENERAL CONDITIONS:

Inspector General. Each party to the agreement shall acknowledge that in accordance with 105 ILCS

5/34-13.1, the Inspector General of the Chicago Board of Education has the authority to conduct certain investigations and that the Inspector General shall have access to all information and personnel necessary to conduct those investigations.

Conflicts – The agreement shall not be legally binding on the Board if entered into in violation of the provisions of 105 ILCS 5/34-21.3 which restricts the employment of or the letting of contracts to, former Board members during the one year period following expiration or other termination of their terms of office.

Indebtedness – The Board's Indebtedness Policy adopted June 26, 1996 (96-0626-PO3), as amended from time to time, shall be incorporated into and made a part of the agreement.

REASONS FOR
PROJECT
AND NOTES

Work for this project will be phased over two fiscal years. include roof replacement, masonry rebuild and tuck- window replacement for approximately half of the building	4
as at both the East and West end of Walter Payton College tly leaking due to poor construction. To alleviate these d with the water infiltration, resultant water damage and . The following is required: Replace water-damaged , provide new access doors and painting. Replace louvers sill flashing and counter flashing. Add new roof drain at py. Correct emergency generator exhaust deficiencies, ation for exhaust piping, and test and commission emergency system supporting the auditorium.	4
perform emergency masonry repairs including partial arapets, temporary nutting and removal of face brick.	1
rical and data infrastructure in the existing lab for a er layout.	8

2015
f 17 [REDACTED]
[REDACTED]
[REDACTED]

3
10.00)
10.00)

50.00
50.00

58.00
75.00
105.00
38.00

:17.60

17.60
INGE_09

015

17

per

.14
1.14

3.00

).75
.75

.44

.00
.00

2E_09

February 2015

These change order approval cycles range from 12/01/14 to 12/31/14

CHANGE ORDER LOG

Board Rpt Number	Reason Code	Code Compliance	Site Inspect Direction	Total % of Contract	Revised Contract Amount	Total Change Orders	Number Change Orders
\$2,206.92	2812444			15.20%	\$332,062.80	\$43,802.80	4

Project Total		\$12,159.80
Reason Code	Reason Description	Amount
2730027	C window unit/bracket in existing window wall. existing window wall. opening for VTAC into new metal panel. [AC in front of existing CMU wall. height wall. Prime and paint.	\$1,471,800.00 12.61%
13-1120-PR5	from science classrooms to prep room 101A. science classroom to prep room 101A doors. in the main office were demolished and need to be replaced. Reroute conduit and wiring ndbow mullion. Provide new receptacle and keyed switch. Connect to existing circuit. ping had a different configuration within the stud wall than anticipated. These plumbing hood. ish 3/4" hot and cold water connections back to the tee for the new 3/4" hot and cold	\$9,481.00
Omission - AOR	exposed high along the wall to the south end of the cabinet. Provide new sanitary, hot ing work is complete.	\$2,830.00
Discovered Conditions	is per revised drawings attached.	\$7,673.00

D15
17 [redacted] per [redacted] .00 [redacted] .00 [redacted] .00 [redacted] .00 [redacted] .00

2015

17

uber

11.00

7.00

8.00

19.90

19.60

10.43

17.48

7.41

15.84

15.84

GE_09

2015

f 17

mber

09.22

91.00
30.22

21.07

66.95

38.02

60.00
60.00

NGE_09

Date: 1/13/2015
Page: 7 of 17

Board Rpt Number

4	\$42,339.92
	\$2,611.95
Project Total	\$44,951.87

0	\$30,555.04
	\$30,555.04
Project Total	\$30,555.04

7	12-1024-PR8
	(\$18,673.60)
Project Total	(\$18,673.60)

5	\$289.63
	\$289.63
Project Total	\$289.63

13/2015

B of 17

Number

\$1,978.00\$3,583.00
\$678.00
\$4,261.00PR8
55,258.676,108.39
1,367.06PR8
H1:242:00
\$2,930.00
\$7,403.00
\$3,274.00
\$2,188.00CHANGE_09

13/2015
3 of 17

Number

>R8	
6,418.00	
8,836.00	
8,429.00	
)838.00)	
3,192.00	
1,552.00	
0,988.00	
4,933.00	
0,547.00	

11,577.39	
,1,096.00	
5,991.03	
6,664.96	
1,306.91	
2,048.61	
\$554.61	
0,053.84	
3,322.27	
8,787.98	
3,190.36	
,102.71)	
02,491.25	

CHANGE_09

Date: 1/13/2015
Page: 10 of 17

	Total	Oracle PO Number	Board Rpt Number
sed act unt	% of Contract		
49	5.56%		
		Reason Code	
		2733762	
		Discovered Conditions	\$7,901.40
		Project Total	\$7,901.40
.95	5.43%		
		Reason Code	
		2746288	
		Owner Directed	\$19,582.00
		Project Total	\$19,582.00
.22	5.14%		
		Reason Code	
		2740880	
		Discovered Conditions	\$10,828.99
		Project Total	\$10,828.99
.57	5.11%		
		Reason Code	
		2739932	
		Other	\$2,629.57
		Project Total	\$2,629.57
00	5.03%		
		Reason Code	
		2323657	
		Discovered Conditions	\$18,491.00
		Report	M_CHANGE_09

Date: 1/13/2015
 Page: 11 of 17

G	Total Change Orders	Revised Contract Amount	Total % of Contract	Oracle PO Number	Board Rpt Number
	\$157,612.00	\$3,288,812.00	5.03%		

Associated piping, added circuit setters, as required.
 Reduced noise level is acceptable to building owner supply airflow from AHU-3 a maximum

Reason Code	2223657	12-0425-PR9
Discovered Conditions		\$45,910.00
Discovered Conditions		\$7,669.00
Project Total		\$72,070.00

\$108,076.94 \$2,295,660.83 4.94%
 Reason Code
 2803551
 It was necessary to cap the duct and infill
 wall in the teacher's lounge. The scope of
 work included installing an access panel.
 Every classroom of the south building;
 room was too large to accommodate the
 handles and additional keys and keying
 casework is damaged at the end panels.

Reason Code	2803551	\$2,053.09
Discovered Conditions		\$2,822.13
Discovered Conditions		\$16,079.16
Project Total		\$847.29

\$590,699.02 \$13,394,017.02 4.61%
 Reason Code
 2411565
 Allowance Credit
 (\$461.61)
 Project Total
 (\$461.61)

5 7

1 3 2 4 5 6 7 8 9

10

2015
of 17

mber

46.44

04.94
51.38

44.90

77.70
22.6063.00
63.0028.11
12.79
40.90

\GE_09

Date: 1/13/2015
Page: 14 of 17

Board Rpt Number

985	d	\$3,170.92
	onditions	\$1,895.01
	onditions	\$8,552.10
	roject Total	\$13,618.03

388	nditions	\$8,004.50
	nditions	\$2,906.35
	nditions	\$2,273.32
	nditions	\$2,857.24
	nditions	\$1,874.75
	roject Total	\$17,916.16

144	nditions	\$7,442.57
		\$2,465.97

5

7

L

D.

10

21

75

100

100

100

100

100

100

100

100

Date: 1/13/2015
Page: 16 of 17

Oracle PO Number	Board Rpt Number
[REDACTED]	[REDACTED]

Project Total	\$2,428.56
Project Total	\$2,428.56
Project Total	\$2,428.56

Project Total	\$2,011.92
Project Total	\$2,011.92
Project Total	\$2,011.92

Project Total	(\$2,183.00)
Project Total	(\$2,183.00)
Project Total	(\$2,183.00)

Project Total	\$2,739.20
Project Total	\$2,739.20
Project Total	\$2,739.20

February 2015

These change order approval cycles range from 12/01/14 to 12/31/14

Date: 1/13/2015
Page: 17 of 17

CHANGE ORDER LOG

Original Contract Amount	Number Change Orders	Total Change Orders	Revised Contract Amount	Total % of Contract	Oracle PO Number	Board Rpt Number
\$839.08	3	(\$36,001.09)	\$2,048,837.99	-1.73%		
					Reason Code 2808701	
					Allowance Credit (\$48,628.81)	
					Project Total (\$45,889.61)	
\$800.00	5	(\$46,701.14)	\$1,302,098.86	-3.46%		
					Reason Code 2734559	
					Permit Code Change \$8,811.86	
					Project Total \$8,811.86	
\$541.00	1	(\$2,051.82)	\$46,489.18	-4.23%		
					Reason Code 2660049	
					Allowance Credit (\$2,051.82)	
					Project Total (\$2,051.82)	
Change Orders for this Period						\$1,191,898.78